

Part Number Update

Bulletin No: PNU-167-000

Effective Date: May 7, 2012


Cancels: N/A

Page: 1 of 1

Subject: **Bendix® AH-4™ Air-Hydraulic Intensifier and Type 50 Rotochamber Obsolescence Notice**

Beginning immediately, the following Bendix® AH-4™ Air-Hydraulic Intensifier part numbers are being made obsolete.

Obsolete Bendix® AH-4™ Air-Hydraulic Intensifier Part Numbers	101107
	101107N
	108639
	286754
	286754N
	287070
	288411
	288411N
	289381
	289382



Bendix® AH-4™
Air-Hydraulic Intensifier
with Rotochamber

See below for maintenance kits still available.

Bendix® AH-4™ Air-Hydraulic Intensifier Master Cylinder Rebuild Kit Part Numbers	Systems Using Brake Fluid	289286
	Systems Using Mineral Oil	289287

Beginning immediately, the following Bendix® Type 50 Rotochamber part numbers are being made obsolete.

Obsolete Bendix® Type 50 Rotochamber Part Numbers	102086
	286745N

Reference Documents

Service Data Sheets

Bendix® AH-4™ Air-Hydraulic Intensifier Service Data sheet SD-11-1357

Bendix® Type 50 Rotochamber Service Data sheet SD-02-1336

The documents shown above are available in the Bendix Document Library at www.bendix.com, or may be ordered from the Literature Center.

Catalog Pages

Bendix® AH-4™ Air-Hydraulic Intensifier Bendix Catalog Page 11-B-01

Bendix® Type 50 Rotochamber Catalog Page 02-S-01 (diaphragms, springs)

The documents shown above are available in the Bendix Document Library at www.bendix.com, or may be downloaded from the Literature Center.